

Multi Pendant Circ

INSTRUCTIONS

THIS FIXTURE REQUIRES 2-3 PEOPLE FOR INSTALLATION. DO NOT ATTEMPT ALONE.

LAMPING

Risk of fire and electrical shock. Installation requires knowledge of electrical systems and should be installed by a qualified electrician. If not qualified, DO NOT ATTEMPT INSTALLATION.

To avoid the risk of fire or overheating, do not exceed the recommended wattage.

SHUT OFF ELECTRICAL SUPPLY AT THE CIRCUIT BREAKER

INSTALLATION

fig. A

Remove the fixture from the packaging and place the *Mounting Plate* against the junction box while allowing wires to pass through the central opening. Fasten mounting plate to junction box with the mounting screws (2) provided.

****It is recommended that you clean the clear glass prior to assembly****

fig. B

Feed the cord from the socket cup assembly through the clear outer glass and then through the canopy. Tighten the strain relief in the canopy to the cord at the desired height. Repeat for each cordset. Gang the (3) cords together inside of the canopy:

WHITE to WHITE [neutral]

BLACK to BLACK [hot].

The fixture is now fully assembled and ready to mount.

fig. C

WIRE CONNECTION

Attach the junction box GROUND WIRE to the bare copper GROUND WIRE from the fixture. Fasten with a plastic wire nut. If there is not a ground wire from the junction box, wrap the bare copper ground wire from the fixture around the green screw on the mounting bracket.

Connect the fixture's WHITE [neutral] wire to the NEUTRAL WIRE from the junction box.

Connect the fixture's BLACK [hot] wire to the HOT WIRE from the junction box.

****see diagram on reverse side****


fig. D

Tuck the wired connections into the junction box and position the fixture's *Canopy* correctly over the *Mounting Plate*. Align the (3) screw holes with the *Mounting Plate* and fasten the *Canopy* to the *Mounting Plate*.

Install lamping [not provide]

Slide white glass *Diffuser* into the clear glass *Diffuser* and attach to *Socket Cup*. A 1/3 turn will lock the *White Diffuser* in place.

Restore power to the junction box.



CARE INSTRUCTIONS


Wipe with a soft cloth only.

Always avoid using harsh chemicals and/or cleaners.


A



B



C



D



Multi Pendant Circ

INSTRUCTIONS

